




Atera SIGNO

Hyundai
i20 01/2015-



Atera SIGNO

Hyundai
i20 01/2015 -
(nicht für Modelle mit Panoramadach geeignet /
not suitable for models with panoramic roof)


Part-No. : 044 321
Part-No. : 045 321







nur bei / only for Part-No.: 045 321




8





- nur bei Art.Nr.: 045 321
only for part no.: 045 321
- | | |
|---------------|-----------------|
| A- 9919700065 | 11- 9910700035 |
| B- 9945700111 | 12- 9908700010 |
| C- 9918700253 | 13- 9922700204 |
| | 14- 9918700472 |
| | 15a- 9949700600 |
| | 15b- 9949700601 |
| | 15c- 9949700601 |
| | 15d- 9949700600 |
| | 16- 9918700654 |
- | | |
|----------------|--|
| 1- 9945700090 | |
| 2- 9919700062 | |
| 3- 9945700105 | |
| 4- 9912700051 | |
| 5a- 9918700526 | |
| 5b- 9918700527 | |
| 6- 9918700250 | |
| 7- 9918700249 | |
| 8- 9910700004 | |
| 9- 9908700231 | |
| 10- 9908700063 | |
- | | |
|---|------------|
|  | SW5 |
|  | 9922700055 |
|  | TX30 |
|  | 9904700387 |

9



Part-No. : 044 321



Atera
MADE IN GERMANY

Atera GmbH
Im Herrach 1
D-88299 Leutkirch
Internet: www.atera.de




© ATERA GmbH
Ref.-Nr.: 044 321_096434432100_992570050200
Ref.-Nr.: 045 321_096434532100_992570050200
Stand/State: 24/03/2015 - Rev 00 Ver 00

Atera SIGNO

Hyundai
i20 01/2015-

Atera SIGNO

Hyundai
i20 01/2015-



INFO

